Application No.: 09/380,614 Examiner: N. W. Woodall

Art Unit: 3733

REMARKS

Reconsideration of the pending application is respectfully requested on the basis of

the following particulars:

Rejection of claims 1 and 2 under 35 U.S.C. § 103(a)

Claims 1 and 2 presently stand rejected as being unpatentable over Byrd (U.S.

5,466,237) in view of Blackburn (U.S. 2,108,957). This rejection is respectfully traversed

for at least the following reasons.

Claim 1 is amended to incorporate the features set forth in claim 2, and claim 2 is

cancelled accordingly.

Amended claim 1 sets forth a nut comprising a plate mounted in free rotation in,

and extending diametrically across, an open cylindrical inner part of the nut, the plate

having a width such that two lateral clearances are defined on either side of the plate in

order to allow passage of the branches of the fixing head inside the nut, whereby the plate

is allowed to slide between the branches, and wherein the two lateral clearances are

configured to permit the insertion of two pins of an auxiliary tool for gripping the nut in

order to facilitate assembly of the nut on the fixing head.

By this arrangement, the lateral clearances accommodate both the branches of the

fixing head and the two pins of an auxiliary tool, such that the auxiliary tool can be used to

turn the nut onto the fixing head.

It is respectfully submitted that Byrd and Blackburn, either individually or in any

combination, fail to disclose or suggest all of the elements of claim 1.

In particular, these references fail to disclose or suggest a nut comprising a plate

mounted in free rotation in, and extending diametrically across, an open cylindrical inner

part of the nut.

The examiner recognizes this deficiency in Byrd, noting that "Byrd fails to disclose

the device wherein the threaded nut further includes a plate mounted in free rotation in the

Application No.: 09/380,614

Examiner: N. W. Woodall

Art Unit: 3733

bore of the threaded nut wherein the width of the plate defines two lateral clearances

capable of allowing the branches of a fixture [to] pass through." (page 3 of the Office

action).

. . . . .

It is respectfully submitted that Blackburn also fails to disclose or suggest a

threaded nut further including a plate mounted in free rotation in the bore of the threaded

nut.

Blackburn discloses a cupped washer or bearing element 16 rotatably mounted

over a boss 15, formed around an inner face of the nut. (see Blackburn; 1st col. of page 2,

lines 45-50). However, referring especially to Blackburn's Figs. 2, 3, and 6, it can be seen

that this washer 16 is not mounted within the bore of nut 13, but as Blackburn explains, is

mounted over the boss 15, which is external to the bore of the nut 13.

Therefore, it is respectfully submitted that while elements of the washer 16, or

elements fixed to the washer 16 such as looped brace 19 extend into the bore of the nut 13,

none of these elements are "mounted in free rotation in" an open cylindrical inner part of

the nut 13.

Further, it is respectfully submitted that the references together fail to disclose or

suggest that two lateral clearances are defined on either side of the plate in order to allow

passage of the branches of the fixing head inside the nut, whereby the plate is allowed to

slide between the branches, and the two lateral clearances are configured to permit the

insertion of two pins of an auxiliary tool for gripping the nut in order to facilitate assembly

of the nut on the fixing head.

As the examiner has recognized, Byrd does not disclose or suggest the plate

mounted in free rotation in, and extending diametrically across, an open cylindrical inner

part of the nut. Accordingly, Byrd cannot disclose or suggest that two lateral clearances

are defined on either side of such a plate in order to allow passage of the branches of the

fixing head inside the nut, and Byrd further cannot disclose or suggest that the two lateral

clearances are configured to permit the insertion of two pins of an auxiliary tool for

gripping the nut in order to facilitate assembly of the nut on the fixing head.

Application No.: 09/380,614

Examiner: N. W. Woodall

Art Unit: 3733

Blackburn also fails to disclose or suggest that two lateral clearances are defined

on either side of such a plate in order to allow passage of the branches of the fixing head

inside the nut, and that the two lateral clearances are configured to permit the insertion of

two pins of an auxiliary tool for gripping the nut in order to facilitate assembly of the nut

on the fixing head.

. . . .

Construing, arguendo, Blackburn's washer 16 and the rib 18 and brace 19 to

correspond to the claimed plate, there is no teaching or suggestion of two lateral

clearances configured to permit the insertion of two pins of an auxiliary tool for gripping

the nut in order to facilitate assembly of the nut on the fixing head, in addition to allowing

passage of the branches of the fixing head inside the nut.

On the contrary, referring to Blackburn's Figs. 5 and 10, it can be seen that the legs

2 and 3 of the keeper lug 1 entirely fill the spaces on either side of the rib 18 of the washer

16. There is no space provided for the insertion of any pins of an auxiliary tool for

gripping the nut in order to facilitate assembly of the nut onto the keeper lug 1.

Therefore, Blackburn cannot be construed to meet both of the elements of claim 1,

wherein the two lateral clearances accommodate, inside the nut, both the branches of the

fixing head and two pins of an auxiliary tool for gripping the nut.

Not only does Blackburn not disclose or suggest that any lateral clearance is

configured to accommodate two pins of an auxiliary tool for gripping the nut in order to

facilitate assembly of the nut onto the keeper lug 1, Blackburn does not disclose or suggest

any such tool at all, or any type of specialized tool for tightening the nut 13 onto the

keeper lug 1.

Therefore, Blackburn lacks any teaching at all that would lead a person of ordinary

skill in the art to the presently claimed invention.

For at least these reasons, it is respectfully submitted that Byrd and Blackburn fail

to form a prima facie case of obviousness of the presently claimed invention. Therefore

claims 1 and 3-6 are allowable over the cited references, and withdrawal of the rejection is

requested.

Application No.: 09/380,614

Examiner: N. W. Woodall

Art Unit: 3733

List of references cited by the examiner

Applicant notes that, while the claims are rejected in view of Byrd (U.S.

5,466,237) and Blackburn (U.S. 2,108,957), the Byrd patent is not listed on the Notice of

References Cited (form PTO-892) included with the recent Office action, although the

Blackburn patent is listed twice. Applicant requests that the Byrd patent be listed on form

PTO-892 to indicate the examiner's consideration of this reference.

Conclusion

In view of the amendments to the claims, and in further view of the foregoing

remarks, it is respectfully submitted that the application is in condition for allowance.

Accordingly, it is requested that claims 1 and 3-6 be allowed and the application be passed

to issue.

If any issues remain that may be resolved by a telephone or facsimile

communication with the Applicant's attorney, the Examiner is invited to contact the

undersigned at the numbers shown.

Respectfully submitted,

BACON & THOMAS, PLLC 625 Slaters Lane, Fourth Floor Alexandria, Virginia 22314-1176

Phone: (703) 683-0500

Date: September 24, 2007

Attorney for Applicant

Registration No. 47,921